



PTFE back-up ring is mainly used to bear greater pressure in cylinder, hydraulic system or valve to keep effective seal function. It is able to prevent o-ring from extrusion and increase the pressure that o-ring resist.


Split



Spiral



Rubber washer is mainly used for shock absorption application or seal the gap in the static fluid (for example, water, oil, air, chemicals solvent, chemicals, etc.).



ID(MM)	Tol(+/-)
4-14.00	0.13
14.01-15.60	0.18
15.61-25.12	0.23
25.13-29.78	0.25
29.79-34.65	0.28
34.66-44.17	0.33
44.18-50.52	0.38
50.53-66.40	0.46
66.41-75.92	0.51
75.93-94.97	0.61
94.98-107.67	0.69
107.68-126.72	0.76
126.73-133.07	0.94
133.08-158.42	0.89
158.43-183.82	1.02
183.83-209.22	1.14
209.23-234.62	1.27
234.63-278.99	1.40
279.00-405.26	1.65
405.27-430.66	1.91
430.67-456.07	2.03
456.08-.....	0.50%

W(MM)	Tol(+/-)
0-1.68	0.15
1.69-2.51	0.15
2.52-3.40	0.15
3.41-5.16	0.15
5.17-6.73	0.15
6.74-...	0.20

H(MM)	Tol(+/-)
0-1.68	0.08
1.69-2.51	0.10
2.52-3.40	0.10
3.41-5.16	0.10
5.17-6.73	0.10
6.74-...	0.15